Problem:	For new users of an intelligent drive, starting to implement a motion control application can be a quite complex task. You need to know how to hook-up the components of the motion system, to configure them (motor, sensors and drive), test their functionality, identify parameters and tune controllers. Finally, execute a simple movement to validate the basic system functionality and focus on your real motion application.	
Solution:	 Drive : Technosoft Intelligent Servo Drive IPM240 – 5E S/W environment : Technosoft IPM MotionStudio – V2.0.1.1 or above 	
Description:	 This Application Note explains: how to perform the basic hardware connections for IPM240 – 5E and brushless motor with encoder/hall sensors; how to create under the 'IPM Motion Studio' a new project/application for motion control with a brushless motor; how to configure the components of the motion system: motor, sensors, drive; how to test the functionality of the system components; 	

- how to identify the motor parameters and tune the controllers;
- how to run and use data analysis tools;
- how to save your project/application;

Connections:



Figure 1. Power Supply – J1 connector

Figure 2. Motor – J3 connector

©Technosoft 2002

APPLICATION NOTE 075.001 12/20/02



Figure 3. . Encoder - J7 connector (differential encoders)

Figure 4. J8 – Halls connector



Figure 5. RS-232 connection diagram

©Technosoft 2002

Please follow the next steps for a hardware connection of the system components:

- 1. Connect the power supply, the motor, encoder and halls to the IPM240 5E drive as you can see in the Figure 1, Figure 2, Figure 3 and Figure 4 respectively.
- 2. Connect the IPM240 5E drive to the PC computer as you can see in the Figure 5
- 3. If you have also an IO240 board then please connect it to the IPM240 5E drive as you can see in the Figure 6
- 4. First power up the PC
- 5. Secondly power up the drive



Figure 6. Connecting IO240 with IPM240 board

©Technosoft 2002

Project set-up:

 <u>Start the execution of IPM Motion Studio</u>; use the Windows "Start | Programs | IPM Motion Studio | IPM Motion Studio" menu command. A dialog as in Figure 7 should be displayed if the communication with the board is established and operates properly.



Figure 7. IPM Motion Studio opening screen

Remarks: If the board is not detected, the "**Board NOT found**" message is displayed in the bottom of the program window. In this case check first the serial cable and the power supply connections on the IPM240 and PC, exit the program and launch it again. Alternatively, use the "**Tools** | **Refresh Serial Settings**" menu command, to retry to communicate with the drive. If the board was detected, the text "**Board present**" or the board type and version (e.g. "**P075.003.E001.S000A**") is displayed in the bottom of program window. In this case, the communication between the IPM drive and the PC works fine, so you can start to use the program.

©Technosoft 2002

Otherwise, if the problem persists, follow the next steps:

- a. From the **Tools** menu, choose **Options**. This command opens the **Options** dialog box.
- b. Select the Serial port tab from the Options dialog box. Select the "Serial type" (RS-232 for a single axis structure). Try to start using a smaller Baud rate value (as 9600). For single axis structures (only one IPM exists in the system and is connected directly to the PC), set the "Host Address" as 255 (default). Select the correct "COM Port Number" of the PC, where the serial cable was connected. Press the OK button. If the communication with the IPM drive does not operate properly, an error message is displayed "Cannot open the serial port". Check if the selected COM port is correct, and not used by another resource of the PC (as mouse, modem, etc). Try again.
- c. If the communication works properly, pressing the **OK** button will exit the **Options | Serial port** dialog, without an error message, and the "**Board present**" or the board type and version (e.g. "**P075.003.E001.S000A**") is displayed in the bottom of program window.
- d. You can in this case try to increase the baud rate, up to the maximal 115 kbaud allowed by the PC.
- e. If the communication operates usually but gives communication errors from time to time, try to increase the "**Read interval timeout**", "**Timeout multiplier**" and "**Timeout constant**" parameters, from the same **Options | Serial port** settings dialog. Note that this is related to some PCs hardware operation, and that usually the default values for these parameters need not to be modified.
- f. Note that the IPM Motion Studio program can be used offline, with no IPM connected to the PC, or powered-up. All the modeling, project and applications definition, and program wizards can be used to configure and parameterize the system and define the motion. Obviously, no IPM information, motion system parameter identification and measurement data can be performed or displayed.

2. Start a new project

All the applications in IPM Motion Studio are organized as projects. A project is specific for a selected type of IPM drive (IPM100, IPM240 or IPS150) and a specific motor type (DC brushed, brushless or step motor). Press the "**New Project**" button, and select the type of the drive and motor you installed in your system:

"IPM240 ->IPM240 - 5E -> Brushless Motor", in order to create such a new project.

©Technosoft 2002

🥦 Technosoft IPM Notion Studio				
Project Iools Help				
📕 🖪 🕞 🐟 🗙 🖬 🏹 🔚 🖽 🖽 🗐	F 🔗			
IDM240				
IDM640				
IDS640				
IPM100 ►				
Den Proj IPM640 ► IPM24	D-SEL BRUSHLESS MOTOR			
IPS150 ► IPM24)-5RI ▶			
Compose Application IPM24)-8EI ▶			
IPM24) - 8RI 🔸			
Motion Studio				
		<u> </u>		
Exit				
		✓ P075.003.E001.S	000A.	CAP NUM OVR READ

Figure 8. Create a new project in IPM Motion Studio

3. Project diagram structure

A schematic diagram of the motion system will be displayed on the screen. It contains the three basic elements of the system, i.e. the motor and sensors, the drive and, as a separate component, the motion reference generator module. Each of these elements can be selected and will allow you to define the parameters and specific settings associated to that element. Note that the new project is opened with some elements already pre-loaded. You need to change / test / validate these elements, in order to fit to your configuration, as described in the next steps. A small arrow pointing to the left upper corner of the element shows you which element to define/check next.

©Technosoft 2002



Figure 9. Motion system diagram in IPM Motion Studio

4. Choose and test the motor and load

Click on the Motor icon. The motor and load dialog will be opened, as in Figure 10.

The dialog allows you to choose and / or parameterize your motor and sensors. You can select the motor from a predefined database ("**Default Brushless Motors**" or "**User**"). You can also, starting from a given motor, change its parameters, in order to fit your motor characteristics.

Several specific tests can be performed, allowing you to check the correctness of some motor parameters, the correct operation of existing sensors as encoder and/or Hall, and connection of motor to the drive.

WARNING! Note that most of these tests apply power to the motor. Please check carefully the motor parameters, mainly the nominal and maximum current values. Each test applying a voltage to the motor will be performed with a protection limit on the current. If this limit exceeds the motor maximum current, severe damage of the motor can occur!

©Technosoft 2002

In order to perform the tests in the proper order, use the "**Guideline Assistant**" textbox, and follow the steps as described there (the following example is given for a brushless motor used with an IPM240 drive; note that for step motors configurations, different dialogs and tests can be performed):

Step 1. Select your motor from the corresponding database. If your motor does not exist in the database, proceed through all the steps in order to define your motor and sensors data. In either case, use these steps to verify the new functionality.

Brushless Motor and Load					×
Motor Pittman 3441 CAPI BT-232MKA Escap22BC Pittman 3441 use the tests from the Next	Database Default Brush notor from the USER ugh all the next step next steps to verify/de	less motors or Default databa: s in order to define etect the motor and	e. If your motor does your motor and sensors parameters a	e Delete not exist in the rs data. In either case, and operation.	OK Cancel Help
Motor Data Nominal Current Peak Current Maximum speed	1.16 3.6 749	A	Test Pha	se Connections	
Pole Pairs Torque Constant	2 0.025	Nm/A	Detect Nun	nber of Pole Pairs	
Phase Resistance (motor + drive) Phase Inductance (motor + drive)	2.63 0.00023	Ohms 💌 H 💌	Identify Resista	ince and Inductance	
Motor Sensors Encoder No lines/rev Hall Sensors Hall Configuration Sensor Typ Temperature	500 2 • • • PTC	lines 💌	Test connections Test connections	Detect number of lines Detect Hall Configuration	
Motor and Load Data Total Inertia	1E-006	kg m^2 💌	Identify	Total Inertia	

Figure 10. The Motor Dialogue

Step 2. Check the values for *nominal* and *peak currents* (given by the motor catalogue data). Modify these values if needed. Press the **"Test Phase Connections"** button to verify that your motor phases are well connected to the drive. The **"Motor Phases Connection Test**" dialog will open. Check the value of the current to be used during the test, and follow the **"Test Procedure"** steps. The test applies a positive voltage on one motor phase (A) and the negative half of it on the other two phases (B and C). Consequently, the measured currents on two motor phases must be in relation $I_A = -2*I_B$. If the test is passed, it validates the physical connection of

©Technosoft 2002

motor phases to the IPM drive, and the correct operation of the current measurement interface on the drive.

Test Purpose Connection Test	Close
Test parameters	Help
Test Procedure 1. Check the above test parameter 2. Press the Start button 3. Wait untill the test ends and displays the result. The test is passed if phase A current IA ~ Itest and phase B current IB ~ • Itest / 2	
Test Status	
IA 0.485 A -0.87 0 0.87 IB -0.249 A -0.87 0 0.87	

Figure 11. Motor Phases Connection Test

Step 3. Check the *maximum motor speed* value, as a motor catalog data. Modify this value if needed.

Step 4. Check the *number of motor pole pairs*. Modify this value according to motor catalog. In order to check or automatically detect this value, press the "**Detect Number of Pole Pairs**" button. The "**Motor Pole Pairs Detection Test**" dialog will open. Check the value of the current to be used during the test, and follow the "**Test Procedure**" steps. The test successively rotates the motor by one electrical period, and requires you to visually detect one complete mechanical rotation of the motor. Once finished, the test will display the number of pole pairs of the motor.

©Technosoft 2002

Motor Pole Pairs Detection Test	? ×
Test Purpose Detects the number of motor pole pairs. The test requires visual inspection of motor shaft.	Close Help
Test Parameters Itest 0.58 A Current value used during the test	
Test Procedure 1. Check the above test parameter 2. Press the Start button 3. Wait until the Move button is enabled, then mark the position of the motor shaft 4. Press the Move button 5. Check the motor shaft position. Repeat step4 until the motor has done a complete revolution. 6. Press the Stop button 1	
Status	
Result Test completed	
Motor pole pairs 2	

Figure 12. Motor Pole Pairs Detection Test

Step 5. Check the *torque constant* value, as a motor catalog data. Modify this value if needed.

Step 6. Check the *phase resistance* and *inductance* values (these are the motor catalogue data). Modify these values if needed. Press the "Identify Resistance and Inductance" button to automatically detect these parameters. The "Motor Resistance and Inductance Identification Test" dialog will open. Check the value of the current to be used during the test, and follow the "Test Procedure" steps. The test will finally identified values differ from the catalogue ones, you'll be asked to confirm the replacement of the old parameter values with the newly identified ones.

©Technosoft 2002

Motor Resistance And Inductance Identification Test	? ×
Test Purpose Identifies motor resistance and inductance.	Close
Test Parameters	Help
Itest 0.58 A Current value used during the test	
Test Procedure	
1. Check the above test parameter 2. Press the Start button 3. Wait untill the the test ends and displays the results	
Test Status	
Test Result	
Test completed	
R = 2.32 ohm L = 0.000243 henry	

Figure 13. Motor Resistance and Inductance Identification Test

Step 7. Check-in the "**Encoder**" checkbox if a quadrature incremental encoder is mounted on your motor shaft. Use the "**Test connections**" button in order to verify the operation of A and B encoder signals. The "**Encoder Connection Test**" dialog will open. Follow the "**Test Procedure**" steps. The test will visually show the motor shaft movement, as measured from the encoder signals. You need to manually move the motor shaft. No voltage is applied to the motor for this test. If either A or B signals are defective, the motor position indicator will not move on the dialog while you move the motor shaft.

Encoder Connections Tes	t		? ×
Test Purpose Checks presence of	encoder signals A and	d B.	Close
Test Procedure 1. Connect the encoder voltage	to the drive and apply the need	ded supply	Help
2. Press the Start button 3. Wait until the test stat 4. Rotate the motor shaf 5. Press the Stop button	us shows "Running test" t manually. Check if position co	Start	
Test Status Step 2 of 2 Running test			
- Test Result			
Phase Currents	Hall sensors	Encoder	
	Halls 110	Position counter 1161	

Figure 14. Encoder Connection Test

©Technosoft 2002

Check the value of the **encoder number-of-lines/revolution** parameter. Press the "**Detect number of lines**" button in order to auto-detect this value. The "**Encoder Counting Direction And Resolution Test**" dialog will open. Check the value of the current to be used during the test, the number of motor pole pairs, and follow the "**Test Procedure**" steps. The test will rotate the motor shaft with one mechanical rotation. The measured number of counts from the encoder will be used to detect the estimated number of encoder lines per revolution. Note that the "**Measured position counter over one revolution**" value is the exact number of encoder pulses measured during this movement. It is 4 times bigger than the number of lines of the encoder over the same movement. The "**Estimated encoder lines** *I* **revolution**" value is computed as the closest standard value corresponding to the measured number of encoder pulses.

Encoder Counting Direction And Resolution Test	? ×
Test Purpose Checks counting direction and estimate the encoder resolution.	Close
Test Parameters Test current 0.58 A Current value used during the test Pole pairs Motor pole pairs Motor pole pairs Test Procedure 1. Connect the Encoder to drive and apply the needed supply voltage 2. Check the above test parameters	Help
3. Press the Start button Test Status	
Test Result Test completed	
Estimated encoder lines/revolution 500 Measured position counter over one revolution 2000	
Phases Hall sensors Encoder	
Halls D10 Position counter 0	

Figure 15. Encoder Counting Direction and Resolution Test

©Technosoft 2002

Step 8. Check in the "**Hall Sensors**" checkbox if Hall sensors are mounted on your motor. Use the "**Test connections**" button in order to verify the operation of the 3 Hall sensor inputs. The "**Hall Signals Connection Test**" dialog will open. Follow the "**Test Procedure**" steps. You need to manually move the motor shaft. The test will visually show the motor shaft movement, and the commutation of different sectors, as defined by the status of the three Hall sensors of the motor. The test is passed if during the motion, all the six possible combinations of the Hall signals are covered. If any of the signals is not changed during the test, it will be reported as defective.

Hall Signals Connection Test	? ×
Test Purpose Checks presence of Hall signals.	Close
Test Procedure	Help
1. Connect the Halls to the drive and apply the needed supply voltage 2. Press the Start button 3. Wait until the test status shows "Running test" 4. Rotate the motor shaft manually. Check that all 6 sectors defined by the Hall inputs were covered 5. Press the Stop button	
Test Status	
Test Result Test completed	
Hall1 Ok Hall2 Ok Hall3 Ok	
Phase Currents Hall sensors Encoder	
Halls 011 Position counter 887	

Figure 16. Hall Signals Connection Test

Check the *Hall configuration* parameter value. Press the "Detect Hall Configuration" button to auto-detect the sequence of Hall sensor connection to the drive (Hall Configuration parameter). The "Hall Configuration Detection Test" dialog will open. Check the value of the current to be used during the test, and follow the "Test Procedure" steps. The test will rotate the motor shaft and detect, from two successive Hall sensors combinations, the Hall configuration parameter (there are 12 different possible configurations) needed to drive the motor.

©Technosoft 2002

Configuration Detectio	n Test	
Test Purpose Detects Hall signals	sequence.	Close
Test Parameters		Help
Itest 0.58	A	- Current value used during the test
Fest Procedure		
 Connect the Halls to the 2 Check the above test n 	e drive and apply the nee arameter	eded supply voltage
3. Press the Start button		<u>S</u> tart
4. Wait until the test ends	and displays the results	
Fest Status		
		STOP
		900000
Test completed		
Hall Con	figuration 2	
Phases	Hall sensors	Encoder

Figure 17. Hall Configuration Detection Test

Step 9. Check in the "**Temperature**" checkbox if you have connected an output of the motor temperature sensor to the corresponding connector pin of the IPM. Check the values of the temperature sensor parameters.

Step 10. Check the value of the *Motor and Load - Total Inertia*. Press the "Identify Total Inertia" button to auto-detect this parameter. The "Total Inertia Identification Test" dialog will open. Check the value of the test current and that of the current protection to be used during the test and follow the "Test Procedure" steps. The test will rotate the motor and estimate the total inertia (motor + load), as reported at motor shaft.

Please note that this test will try to impose a constant torque in the motor. In case that you have a new motor that was not chosen from the motor database, you need to perform the tuning of the current controller before running this test. The current controller tuning can be validated in the Drive dialogue.

©Technosoft 2002

Total Inertia Identification Test	? ×
Test Purpose Identifies total inertia (motor + load) seen at motor shaft.	Close
Test Parameters	Help 'V
Itest 0.58 🛛 🗹 🔽 - Current value used during	g the test
Iprot 3.6 A Maximal current protection	n level
Test Procedure	
1. Check test parameters 2. Press the Start button 3. Wait until the test ends and displays the results	tart
Test Status)
Test Result	
Test completed	
J total 1.58E-006 kg * m^2	

Figure 18. Total Inertia Identification Test

Step 11. Exit the Motor and Load dialog, by pressing the OK button.

5. Define the control scheme, tune and test controllers

Click on the **Drive** icon. The drive dialog will be opened, as in Figure 19.

The dialog allows you to choose and parameterize the control scheme to be implemented in your application. You can select which control loops to be activated in the scheme, tune and test the activated controllers, and also select and setup the protections of the drive.

Several specific tests can be performed, allowing you to check the behavior of the control loops.

WARNING! Note that most of these tests apply power to the motor. Please check carefully the motor parameters, mainly the nominal and maximum current values. Each test applying a voltage to the motor will be performed with a protection limit on the current. If this limit are exceeds the motor maximum current, severe damage of the motor can occur!

In order to perform the tests in the proper order, use the "**Guideline Assistant**" textbox, and follow the steps as described there.

©Technosoft 2002

Drive	X
Guideline Assistant Motion r Step 1. Select your controller scheme configuration. Check the corresponding interm controller (speed, position) and the interm commutation scheme (PMSM or BLDC) to be interm used. Note that the PMSM mode requires an info Drive encoder, and that BLDC mode requires Hall Image: Speed Controller Drive Operation Parameters V Detect Vdc 15.3616 V Detect Current limit 1 A Image: Speed Controller Ki 0.016 Tune Ki 0.0016 Test Integral limit 1 Z Image: Speed Controller	eference uted by al reference ator mal, read from g input Protections ✓ Overvoltage Trigger if Vdc > Vmax ✓ Undervoltage Trigger if Vdc > Vmax ✓ Overcurrent Trigger if Imotor > Imax 2.55 for a time interval > I max trigger time Output I all trigger if Dos. er. > Err. max for a time interval > Er max trigger time Motor temperature ✓ Drive temperature Trigger if T > T2max 80 Current Current Trigger if T > T2max 10 Current Current Current Control error Trigger if T > T2max 10 Current Curr
Position Controller Kp 100 Ki 2.5 Kd 0 Kd filter 0.1 Integral limit 0.001 % Speed limit 314 rad/s	Start mode Start mode Start Setup Current used (% of motor nominal I start) 50 Time to align on phase A time_A 0.5 Time to align on phase B time_B 0.5 S

Figure 19. The Drive dialog

Step 1. Select your controller scheme configuration. Check the corresponding controllers (speed, position) and commutation scheme (**PMSM** or **BLDC**) to be used. Note that the PMSM mode requires an encoder, and that BLDC mode requires Hall sensors mounted on the motor shaft. Thus, if these sensors were not defined in the motor dialog, the associated control scheme is not selectable.

Step 2. In the "**Motion reference**" group-box, select the motion reference type to be used when the motion will be executed. Use the "**Internal Reference Generator**" selection for motions generated through TML motion commands. In this case, the reference will be defined at a latter stage, in the "**Motion**" block of the motion system diagram. If an external analog reference is used during the motion, use the "**Setup Range**" button to set up its parameters.

©Technosoft 2002

Step 3. In the "**Drive Operation Parameters**" group-box set the value of the DC voltage power supply (**Vdc**). Use the "**Detect**" button to measure its actual value as applied to the drive. The "**V**_{DC} **Detection Test**" dialog will open. The test will measure the actual value of the power supply voltage applied to the IPM drive.

DC Detection Test		? ×
-Test Purpose Identifies the VDC voltage.		Close
Test Procedure		¹ Help
 Press the Start button Wait until the test ends and displays the results 	<u>S</u> tart	
- Test Status	STOP	
Test Result Test completed		
VDC 16.3 V		

Figure 20. V_{DC} Detection Test

Also set the "**Current Limit**" parameter, e.g. the maximum current value, controlled by the drive during motion.

Step 4. In the "**Current Controller**" group-box you can set the current controller parameters **Kp** (proportional) and **Ki** (integral).

Use the **"Tune**" button to compute these parameters based on the imposed dynamical performances of the closed loop, and on the system parameters. The **"Current Controller -Tuning**" dialog will open in this case. If you set the *dump factor* and the *passband* of the closed control loop, the program will automatically compute the controller coefficients, based also on motion system parameter values. Expected system response to a step reference input in the controller is graphically displayed, as well as the frequency characteristic of the closed loop structure. Once you exit this dialog by pressing the **OK** button, the newly computed controller parameters replace the previous values.

If you are not comfortable with the damp factor and passband parameters, you may cancel the Current Controller – Tuning dialogue and type directly the **Kp**, **Ki** coefficient values in the Current Controller group-box:

Current Controller							
Кр	0	Tune					
Ki	0.526	Test					

Figure 21. Current Controller group-box

©Technosoft 2002

Current Controller - T	uning -	Applicat	ion Untitl	ed1					? ×
								1	_
Name	Val	Unit	Min			Max			+ 1
Dump_C - Damping	1		0			- 2		0.4	\pm
PB_C - Pass Band CL	2000	rad/s	1000		— <u> </u>	- 2500		0.2	+
	_							0 0.005 0.01 0.015 0	0.02
								Time [s]	
								Current	
	Name			Val	Unit			-10	
Ki_C_real - Current co	ntroller in	tegral fac	tor	0.526				-15	
Kp_C_real - Current co	ontroller p	proportion	al factor	0				-20	_
								0 7.5 15 22.5 30	2
								Frequency [rad/s] ×*	1e3
1								Amplitude of Transfer Function [db]	
					0	K Cance	H	lelp	

Figure 22. Current Controller Tuning

Use the "**Test**" button in order to test the step response of the closed current loop, for the actual values of the controller parameters. The "**Current Controller Tuning Test**" dialog will open.

The test has two phases:

- Set-up test parameters ('Test parameters' tab)
- Run the test. ('**Test**' tab)

In the '**Test Parameters**' tab you ca define the test parameters: check the value of the current reference to be used during the test, as well as the protection current value.

The test applies power to the motor. It applies a step current of "Test current" value, to the motor. The reference (IQREF) and measured (IQ) currents, as well as the reference voltage (UQREF) applied to the motor during the test are then displayed at the end of the test.

The test controls the current applied to the motor as imposed by the user, as the "Test current" parameter from the "Test Parameters" group box. When entering the dialog, the program suggests a value for this current, computed as the half of the nominal motor current. You may change this value, within a specific range, limited by motor and drive maximum accepted currents. The "Iprotection" parameter is used to set the value of the current for which the over current protection will be activated during the test. If this value is reached during the test, then the test execution is stopped. See the time diagram included in the dialog in order to have a better understanding of the meaning of these parameters.

In order to perform the test, follow the "Test Procedure" indications.

©Technosoft 2002

Current Controller Tuning Test	?×
Test Parameters Test	
Test purpose Checks current controller step input response.	OK
Test procedure 1. Check/setup the test parameters below 2. Go to the "Test" tab 3. In the "Test" tab, press the "Start" button 4. Wait until the test ends and displays the results 5. If needed, change the controller parameters and repeat steps 3 and 4 until you get satisfactory results	Cancel Help
Test parameters Test current 0.58 A I I protection 3.6 A I I Protection	

Figure 23.a. Current Controller Tuning Test – 'Test Parameters' settings

The '**Test**' tab is used to run the test. In this "**Test**" tab press the Start button and wait until the test ends and displays the results.

If needed, change controller parameters and repeat the procedure (press the Start button etc.) until you get satisfactory results.

You can change the controller parameters by modifying the value of the parameter in the corresponding edit box or by dragging the associated slider. To modify the range of values for the slider you can use the spin buttons (for minimum and for maximum limit values).

Note that the current min/max range is a sub-range of the absolute range. The absolute limits are computed and depend on specific scaling factors and parameters of the system. Note that a sub-range of the maximum absolute range will allow fine adjustments of the parameters and eventually will reduce the risk of unstable control loop behavior at sudden changes of parameter value.

©Technosoft 2002



Figure 23.b. Current Controller Tuning Test – 'Test' running

If the test fails, check the following:

- Check if the Technosoft drive is powered correctly (use for example, the "VDC Detection Test" from the Drive dialog, to measure the DC-link voltage applied to the power transistors of the Technosoft drive)

- Check if motor phases are connected to the drive

- Check if motor phases are not interrupted by measuring its phase-to-phase resistance (use an ohmmeter; disconnect the motor from the Technosoft drive before performing this measurement)

The test will be validated through visual inspection of the graphical test results. If the controlled current reaches the reference current with acceptable performances (response time, overshoot, final error), you can validate the controller coefficients. Otherwise, change their parameters and execute the test until the results are satisfactory.

Pressing the OK button will save the actual values of controller parameters and return into the Drive dialogue. Pressing Cancel button will leave controller parameters unchanged.

Note. You can save the results of a test, using the "Save Plots" button. You can also re-load results of previously saved tests, using the "Load Plots" button.

©Technosoft 2002

Step 5. In the "**Speed Controller**" group-box set the speed controller parameters **Kp** (proportional), **Ki** (integral) and **Integral limit** (saturation limit for the integral term of the controller).

Use the **"Tune**" button to compute these parameters based on the imposed dynamical performances of the closed loop, and on the system parameters. The **"Speed Controller -Tuning**" dialog will open in this case. If you set the *dump factor* and the *passband* of the closed control loop, the program will automatically compute the controller coefficients, based also on motion system parameter values. Expected system response to a step reference input in the controller is graphically displayed, as well as the frequency characteristic of the closed loop structure. Once you exit this dialog by pressing the **OK** button, the newly computed controller parameters replace the previous values.

If you are not comfortable with the damp factor and passband parameters, you may cancel the Speed Controller – Tuning dialogue and type directly the **Kp**, **Ki** coefficient values in the Speed Controller group-box:

- Speed Contro	oller — — — — — — — — — — — — — — — — — — —		
Кр	0.016		Tune
Ki	0.0016		Test
Integral limit	10	% 🔽	

Figure 24. Speed Controller group-box



Figure 25. Speed Controller Tuning

©Technosoft 2002

Use the "**Test**" button in order to test a ramp response of the closed speed loop, for the actual values of the controller parameters. The "**Speed Controller Tuning Test**" dialog will open.

The test has two phases:

- Set-up test parameters ('Test parameters' tab)
- Run the test. ('**Test**' tab)

In the '**Test Parameters**' tab you ca define the test parameters: check the value of the speed reference to be used during the test, as well as the protection and limit current values.

The test applies power to the motor. It applies a speed profile (see graphical diagram), to the motor.

The "Ilimit" parameter is the value at which is limited the current value during the test, by the current controller. The "Iprotection" parameter is used to set the value of the current for which the over current protection will be activated during the test. If this value is attained during the test, the test execution is stopped. The "Istart "parameter is the value of the current used during the initial positioning of the motor (note that this parameter is needed only for a brushless motor, operating in the PMSM mode). See the time diagram included in the dialog in order to have a better understanding of the meaning of these parameters.

The test controls the speed applied to the motor as imposed by the user, as the speed profile from the "Test Parameters" group box. When entering the dialog, the program suggests a value for the Upper and Lower speed. You may change these values, in a specific range, limited by motor maximum accepted speed.

Trapezoidal or ramp profiles can also be generated, setting the acceleration and deceleration time intervals, tap and/or tan. Single or repetitive cycle movements can be selected using the Multiple Cycle Movement checkbox.

In order to perform the test, follow the "Test Procedure" indications.

©Technosoft 2002

Test Parameters	Test		
Test purpose Checks speed	i controller ste	p input response.	
Test procedure 1. Check/setup the 2. Go to the "Test" 3. In the "Test" tab, 4. Wait until the test 5. If needed, chang	test current limits ar tab , press the "Start" b t begins and display le the controller para	nd speed profile below nutton is the results ameters during the test, until you get satisfactory results	OK Cancel Help
Current limits protection 3.6 I limit 1 I start 50	A A 2	Test speed	
Test speed profile Upper speed 149.8	tp ad/s ▼ · + -		ltiple cle vement
Lower speed	ad/s 💌 🕹 t		

Figure 26.a. Speed Controller Tuning Test – 'Test Parameters' settings

The '**Test**' tab is used to run the test. In this '**Test**' tab press the Start button and wait until the test ends and displays the results. If needed, change controller until you get satisfactory results. If On-line plot option is selected, the reference (SPDREF) and measured (ASPD) speed values will be continuously displayed during the test (oscilloscope function). If Data logger option is selected, the reference (SPDREF) and measured (ASPD) speed values, (as well as the reference (IQREF) and measured (IQ) current values), are displayed at the end of the test.

You can change the controller parameters during test execution by modifying the value of the parameter in the corresponding edit box or by dragging the associated slider. To modify the range of values for the slider you can use the spin buttons (for minimum and for maximum limit values). Note that the current min/max range is a sub-range of the absolute range. The absolute limits are computed and depend on specific scaling factors and parameters of the system. Note that a sub-range of the maximum absolute range will allow fine adjustments of the parameters and eventually will reduce the risk of unstable control loop behavior at sudden changes of parameter value.

©Technosoft 2002

APPLICATION NOTE 075.001 12/20/02



Figure 26.b. Speed Controller Tuning Test – 'Test' running

If the test fails, check the following:

- Check if the Technosoft drive is powered correctly (use for example, the "VDC Detection Test" from the Drive dialog, to measure the DC-link voltage applied to the power transistors of the Technosoft drive)

- Check motor phases connections (use for example, the "Test Phases Connections" from the Motor dialog)

- Check if the position sensor operates properly (use the tests associated to the position sensors from, the Motor dialog)

- Check motor parameters (eventually using the motor parameters identification tests from the Motor dialog)

- Check current controller parameters (use the "Current Controller Tuning Test")

©Technosoft 2002

Test validation. The test will be validated through visual inspection of the graphical test results. If the controlled speed reaches the reference speed with acceptable performances (response time, overshoot, final error), you can validate the controller coefficients. Otherwise, change their parameters and execute the test until the results are satisfactory.

Pressing the OK button will save the actual values of controller parameters and return into the Drive dialogue. Pressing Cancel button will leave controller parameters unchanged.

Note. You can save the results of a test, using the "Save Plots" button. You can also re-load results of previously saved tests, using the "Load Plots" button.

Step 6. In the "**Position Controller**" group-box set the position controller parameters **Kp** (proportional), **Ki** (integral), **Kd** (derivative), **Kd filter** (filtering coefficient for the derivative term). Set also the **Integral limit** (saturation limit for the integral term of the controller) and **Speed limit** (saturation limit for the position controller output, seen as a speed reference value).

Use the **"Tune**" button to compute these parameters based on the imposed dynamical performances of the closed loop, and on the system parameters. The **"Position Controller -Tuning**" dialog will open in this case. If you set the *dump factor* and the *passband* of the closed control loop, the program will automatically compute the controller coefficients, based also on motion system parameter values. Expected system response to a step reference input

in the controller is graphically displayed, as well as the frequency characteristic of the closed loop structure. Once you exit this dialog by pressing the **OK** button, the newly computed controller parameters replace the previous values.

If you are not comfortable with the damp factor and passband parameters, you may cancel the Position Controller – Tuning dialogue and type directly the **Kp**, **Ki**, **Kd**, **Kd** filter coefficient values in the Position Controller group-box:

Position Cont	roller		
Кр	100		Tune
Ki	2.5		Test
Kd	0		
Kd filter	0.1		
Integral limit	0.0001	% 💌	
Speed limit	314	rad/s 💌	

Figure 27. Position Controller group-box

©Technosoft 2002

APPLICATION NOTE 075.001 12/20/02

Name	Val	Unit	Min			Max		1 0.75
oump_P - Dump factor	1		0		-t	2		0.5
itter_D - Filter	0.1		0		45	1		0.25
PSatP - I⊓tegral part	0.001	%	0			100		0 0.05 0.1 0.15 0.2
imit_Speed - Maximal	314	rad/s	1			3000		
B_P - Pass Band PL	50	rad/s	1			32767	-	
	Name			Val	Unit			
d_P_real - Real positio	on contre	oller deriv	ative factor	[,] 0				-10
i_P_real - Real positio	n contro	ller integra	al factor	2.5				-25
p_P_real - Real position	on contre	oller propo	ortional fact	100				0 0.75 1.5 2.25 3
								Frequency [rad/s] ×1e
							1	

Figure 28. Position Controller Tuning

Use the "**Test**" button in order to test the step response of the closed position loop, for the actual values of the controller parameters. The "**Position Controller Tuning Test**" dialog will open.

The test has two phases:

- Set-up test parameters ('Test parameters' tab)
- Run the test. ('**Test**' tab)

In the '**Test Parameters**' tab you ca define the test parameters: check the value of the position reference to be used during the test, as well as the protection and limit current values.

The test applies power to the motor. It applies a position profile to the motor.

The "Ilimit" parameter is the value at which is limited the current value during the test, by the current controller. The "Iprotection" parameter is used to set the value of the current for which the over current protection will be activated during the test. If this value is attained during the test, the test execution is stopped. The "Istart "parameter is the value of the current used during the initial positioning of the motor (note that this parameter is needed only for a brushless motor, operating in the PMSM mode). See the time diagram included in the dialog in order to have a better understanding of the meaning of these parameters.

The test controls the position applied to the motor as imposed by the user, as the position profile from the "Test Parameters" group box. When entering the dialog, the program suggests a value for Upper and Lower position. You may change these values.

©Technosoft 2002

Trapezoidal or ramp profiles can also be generated, setting the acceleration and deceleration time intervals, tap and/or tan. Single or repetitive cycle movements can be selected using the Multiple Cycle Movement checkbox.

In order to perform the test, follow the "Test Procedure" indications.



Figure 29.a. Position Controller Tuning Test – 'Test Parameters' settings

The '**Test**' tab is used to run the test. In this '**Test**' tab press the Start button and wait until the test ends and displays the results. If needed, change controller parameters and repeat the procedure (press the Start button etc.) until you get satisfactory results.

If On-line plot option is selected, the reference (TPOS) and measured (APOS) position values will be continuously displayed during the test (oscilloscope function). If Data logger option is selected, the reference (TPOS) and measured (APOS) position values, (as well as the reference (SPDREF) and measured (ASPD) speed values), are then displayed at the end of the test.

©Technosoft 2002

You can change the controller parameters during test execution by modifying the value of the parameter in the corresponding edit box or by dragging the associated slider. To modify the range of values for the slider you can use the spin buttons (for minimum and for maximum limit values).

Note that the current min/max range is a sub-range of the absolute range. The absolute limits are computed and depend on specific scaling factors and parameters of the system. Note that a sub-range of the maximum absolute range will allow fine adjustments of the parameters and eventually will reduce the risk of unstable control loop behavior at sudden changes of parameter value.

Position Controller Tur	ing Test				?×
Test Parameters	Test				ОК
Position controller parar Kp 100	neters	<u>·</u> · · · ·	<u> </u>	· · · ⊡	Cancel
Ki 2.5		<u>·</u> · · · · · · · · · · · · · · · · · ·	<u> </u>		
Integral limit 0.001	*	Ξ∩ 手人・・・		I	Kd filter (01) 0.1
					Speed limit (rad/s) 314
					Position reference 5.000 rot Motor position 5.000 rot
					C On-line plot Data logger
Status Step 4 of 4 Test running. Press "Sta test	op'' to end th	e <u>S</u> tart	.	Result	

Figure 29.b. Position Controller Tuning Test – 'Test' running

If the test fails, check the following:

- Check if the Technosoft drive is powered correctly (use for example, the "VDC Detection Test" from the Drive dialog, to measure the DC-link voltage applied to the power transistors of the Technosoft drive)

- Check motor phases connections (use for example, the "Test Phases Connections" from the Motor dialog)

©Technosoft 2002

- Check if the position sensor operates properly (use the tests associated to the position sensors from, the Motor dialog)

- Check motor parameters (eventually using the motor parameters identification tests from the Motor dialog)

- Check current controller parameters (use the "Current Controller Tuning Test")

Test validation. The test will be validated through visual inspection of the graphical test results. If the controlled position reaches the reference position with acceptable performances (response time, overshoot, final error), you can validate the controller coefficients. Otherwise, change their parameters and execute the test until the results are satisfactory.

Pressing the OK button will save the actual values of controller parameters and return into the Drive dialogue. Pressing Cancel button will leave controller parameters unchanged.

Note. You can save the results of a test, using the "Save Plots" button. You can also re-load results of previously saved tests, using the "Load Plots" button.

Step 7. In the "**Protections Controller**" group-box, select and parameterize those protections that you want to be activated during the motion. For a first evaluation, use the default settings and selections.

Step 8. For PMSM operating mode, the "**Start mode**" group-box is active. Set up the current value used during the motor start (**Istart**), select the start method to be used, and set up de corresponding parameters. Note that if you select a current mode start, you need the values of current offsets. Use the "**Detect**" button in order to measure these values on your IPM drive.

Step 9. Press the **OK** button of the **Drive** dialog, in order to validate the defined control structure and its associated parameters.

©Technosoft 2002

6. Define and test the motion

Click on the **Motion** icon. The motion wizard dialog will be opened, as in Figure 30.

Insert Motions Events Decisions Free Text Sequence Motions Motions Notations Notations Image: Sequence Motions Notations Notations Notations Image: Sequence Image: Subroutines Interrupts Notations Edit Image: Sequence Image: Subroutines Interrupts Edit Image: Sequence Code Edit View Code Image: Sequence Move Up Move Up Move Up Image: Sequence Duplicate Subroutines Subroutines
Image: Image
Code Edit View Code Move Up Move Down Duplicate
View Code Move Up Move Down Duplicate
Move Up Move Down Duplicate
Move Down Duplicate
Duplicate
Delete
Import
Exect.
Groun
Ungroup
Enable
Disable
ОК
Cancel
Help

Figure 30. The Motion Wizard dialog

The dialog allows you to insert specific motion sequences and other TML commands, as arithmetic, I/O operations, events, etc. Details about the functionality and features of the Motion Wizard are given in Chapter 5 of "IPM Motion Studio User Manual".

In order to perform a simple motion, only to validate the complete overview of this paragraph, use the predefined motion sequence already defined in the motion profile by clicking the button

In the associated Motion Profiles dialog window you can define a position profile as you can see in the figure below:

©Technosoft 2002

APPLICATION NOTE 075.001 12/20/02

Motion - Profiles			? ×
	 ● <u>Position</u> ● <u>Belation</u> ● <u>Absol</u> 	ive lute	Execute Immediate Then wait until motion is completed C On Event
Acceleration rate =	1	rad/s^2	Edit Event
Slew Speed =	3000	rpm 💌	
Position Increment =	30	rot	
⊂ Gener values ⊂ Gener values	C Setup motion data, but don't start execution		
	ОК С	Cancel H	elp

Figure 31. The Motion Profiles dialog

You can define the profile parameters, i.e. the acceleration/deceleration, the slew speed, and the reference position value.

Once the motion is defined, exit the Motion Wizard by pressing the **OK** button.

You can now generate the complete TML code associated to the chosen configuration, download it to the IPM drive, and execute it. You simply press the "**Run**" button, and all the operations associated to this command will be executed: reset the IPM, generate the TML code based on the configuration and imposed parameters, as well as on the motion, download the code to the IPM, and start its execution. The motor should execute the imposed motion.

You can upload the data logged during the motion by selecting the data logger window, click the right button of the mouse, and activate the "**Upload Data**" menu command. The variables stored during the execution of the motion will be displayed on the screen.

You can Stop the motor by disabling the PWM outputs (Stop the motion by Axisoff)

X Reset the drive

©Technosoft 2002

APPLICATION NOTE 075.001 12/20/02



Figure 32. The Data Logger dialog

More details about the data analysis tools (Logger and Control Panel) are presented in the IPM Motion Studio User Manual.

7. Save and close the project

The precedent paragraphs guided you through the process of starting a motion project, configuring and parameterizing it, defining the motion and finally executing it on the IPM drive. As one can see from the described procedure, the steps to follow are straightforward, and allow you to validate the operation of your complete drive configuration.

When arrived at this point, you can start and really go into details related to all the features of the program, mainly focusing on the motion description and implementation using TML instructions.

The just defined project, completed with the correct structure definition and parameters of the elements (motor, sensors, controllers, etc.), can be saved for further use. Select the "**Project** | **Close**" menu command. You'll be asked to give a name for the project and the application to be saved. Latter on, you'll be able to open the project, in the same status as when saved the last time.

©Technosoft 2002

Drive layout:



©Technosoft 2002

This page is empty

©Technosoft 2002